

LR Field Services

Prepared for Williams Enterprises (12214)

500 South E Street
Fort Smith AR 72901

Table of Contents

Field Service Ticket	1.0
Field Service Ticket	2.0



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104704
FormID: 24743850

Williams Enterprises (12214)
500 South E Street
Fort Smith, AR 72901

Job Information

1. Hi-Speed Job Number	104704
2. Asset Type	350 hp Hoffman blower
3. Make	
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	Blower 3


Service Call Details

7. Service Objectives

To align motor to blower before startup and then do a hot alignment after running for two hours.

8. Services Performed

Same as objective. The blower shows signs of imbalance but it got better the longer it ran. The coupling has a lot of wear in the gears.



These are our finished numbers after hot alignment.



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

Trevor Hall



11. Customer Signature

George Williams





Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104704
FormID: 24748835

Williams Enterprises (12214)
500 South E Street
Fort Smith, AR 72901

Job Information

1. Hi-Speed Job Number
2. Asset Type
3. Make
4. Model
5. Serial Number
6. Customer Asset ID/Asset Name

Service Call Details

7. Service Objectives
8. Services Performed
9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature
11. Customer Signature

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 06/09/2025

Powered by [INSPECTALL](#)

2.0