

Job Information

Job #:	95776				Date:	September 5, 2019
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name: Hormel Foods Motor#:

Name Plate Information

Manufacturer:	Reliance	Enclosure :	Totally Enclosed Fan Cooled	Horsepower/kW:	40
Serial#:		Model#:		Service Factor:	1.15
Frame:	326TY	Rated RPM:	3555	Rated Voltage:	460
Phase:	3	Rated Amps:	45.3	Cycles:	60

Special design: No

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection

Megs at reasseme	bly:	Good	Surge a	at reassembly:	Good		Hi-pot r	reassembly:	Good
Winding Resistance Incoming									
	Phases	s A to B	Phas	ses B to C	Phases C to	A	F	Resistive imba	alance
Outgoing	0.00		0.00)	0.0			0.00	

Test Run Inspection

Date September 5, 2019

Yes I have merged this motor and verified that all electrical tests are complete!

Power Supply

	Phase A	Phase B	Phase C
No Load Voltage	461	459	460
No Load Current	13	12	12.4

Temperatures: (Degrees Fahrenheit)

Test run ball-bearing motors for 15 minutes.

Test run sleeve bearing motors for 60 minutes.

Temperature rise at the end of test run should be less than 2° every five minutes.

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

Test Run Inspection (Continued)

Ambient Temp:

TIME	DE	Degree Change	ODE	Degree Change
START:				
5 MIN:				
10 MIN:				
15 MIN:				
20 MIN:				
25 MIN:				
30 MIN:	119		116	
35 MIN:				
40 MIN:				
45 MIN:				
50 MIN:				
55 MIN:				
60 MIN:				



Test Run Inspection (Continued)

Vibration Data: In./Sec-Peak	(Readings should be less than .08 In/Sec Peak)			
	Horizontal	VDE	Axial	
DE	0.06	0.08	0.05	
ODE	0.10	0.12	0.03	

Magnetic Center Measurements (Only Applies to Sleeve Bearing Motors)

Magnetic Center line distance from shaft shoulder

Magnetic Center line distance from all the way out mark

Magnetic Center line distance from all the way in mark

Total Motor End Float

Additional photos









Yes, the shaft has been isolated for delivery.

Service Tech name:

Robert Wiley

Service Tech signature:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301