

Job Information

| Job #: | 137000 | | | | Date: | April 3, 2018 |
|-----------|--------|----------------|----|----------------|-------|---------------|
| Priority: | _ | Authorized OT: | No | Authorized by: | | |

Customer Information

Name: USG

Motor#:

Name Plate Information

| Manufacturer: | MARATHON | Enclosure : | Open Drop Proof (ODP) | Horsepower/kW: | 60 |
|---------------|---------------------------|-------------|--------------------------|-----------------|---------|
| Serial#: | M65091199-1-01`/ 11-02 | Model#: | PVA326TTDP1701 0AAL | Service Factor: | 1.15 |
| Frame: | 326TDZ | Rated RPM: | 3550 | Rated Voltage: | 230/460 |
| Phase: | 3 | Rated Amps: | 144/72 | Cycles: | 60 |

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

| Shaft Condition: | _ | Bearings Retainer: | Yes |
|----------------------------|------|--------------------|------|
| Type of grounding device: | | Bearing DE Size: | 6312 |
| Shaft runout(TIR-Inbound): | .001 | Bearing ODE Size: | 6311 |

Retainer condition:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Mechanical Inspection (Continued)

| Seals DE condition : | Worn | Brg. Seats DE: | Good | |
|---------------------------------|---------|--------------------------|--|--|
| Seals DE type: | Slinger | If DE undersized, amt.: | .000 | |
| Seals DE size: | | Brg. Seats ODE: | Good | |
| Seals DE (inbound) condition : | | If ODE undersized, amt.: | 000 | |
| Seals ODE condition : | Worn | Shaft damage: | ОК | |
| Seals ODE type: | Slinger | | | |
| Seals ODE size: | | Bushings/sleeves DE: | Ok | |
| Seals ODE (inbound) condition : | | Bushings/sleeves ODE: | Ok | |
| Endbell fits/damage: | Bad | Foot/Flange condition: | Ok | |
| Endbell DE size: | 5.125 | Foot flatness: | Pass | |
| Endbell DE insulated?: | — | Doop Air Con Most Cus | Does Air Gap Meet Customer or EASA spec(<109 | |
| Endbell ODE size: | 4.725 | variation)? | tomer or EASA spec(<10% | |
| Endbell ODE insulated?: | No | Yes | | |

Conclusion

Service Tech name:

BILLY MAYS

Service Tech signature:

A 0

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254