

Job Information

Job #:	137876				Date:	September 13, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	DESOTOI CO. REGINAL UTILITY	Motor#:

Name Plate Information

N/A	Enclosure :	Open Drop Proof (ODP)	Horsepower/kW:
11DWO8581-03	Model#:	E8K-HD-E2W 8X8	Service Factor:
	Rated RPM:	1320	Rated Voltage:
	Rated Amps:		Cycles:
		11DWO8581-03 Model#: Rated RPM:	(ODP) 11DWO8581-03 Model#: E8K-HD-E2W 8X8 Rated RPM: 1320

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition:	Good	Bearings Retainer:	Yes
Type of grounding device:		Bearing DE Size:	210
Shaft runout(TIR-Inbound):	.001	Bearing ODE Size:	210
Retainer condition:	Good		

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Mechanical Inspection (Continued)

Seals DE condition :	Worn	Brg. Seats DE:	Good
Seals DE type:	Slinger	If DE undersized, amt.:	.000
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	.00
Seals ODE condition :	None	Shaft damage:	ОК
Seals ODE type:	Other		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :	1.501	Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	3.544	Foot flatness:	Pass
Endbell DE insulated?:	No	Doos Air Con Most Cur	tomor or EASA apon(~10%
Endbell ODE size:	3.544	variation)?	stomer or EASA spec(<10%
Endbell ODE insulated?:	_	Yes	

Conclusion

Service Tech name: BILLY MAYS

Service Tech signature:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254