

## **Job Information**

Job #: 138046 Date: September 18,

2018

Priority: — Authorized OT: No Authorized by:

**Customer Information** 

Name: ST.CLAIR FOODS Motor#:

**Name Plate Information** 

Manufacturer: LEROY SOMER Enclosure: Totally Enclosed Horsepower/kW: 12/8.4

Fan Cooled

Serial#: LS132MDPT Model#: 19772ZXA009 Service Factor: N/A

Frame: 132M Rated RPM: 3410/1700 Rated Voltage: 220/200

Phase: 3 Rated Amps: 45/32.5 Cycles: 60

Special design: No

**Mechanical Inspection** 

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6208

Shaft runout(TIR-Inbound): .001 Bearing ODE Size: 6207

Retainer condition: Good



## **Mechanical Inspection (Continued)**

Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Slinger If DE undersized, amt.: .000

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.: .000

Seals ODE condition: Shaft damage: OK Worn

Seals ODE type: Slinger

Bushings/sleeves DE: Ok Seals ODE size:

Bushings/sleeves ODE: Ok Seals ODE (inbound) condition:

> Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 3.150 Foot flatness: **Pass** 

Endbell DE insulated?: No

Endbell ODE insulated?:

variation)? Endbell ODE size: 2.837

Yes

Does Air Gap Meet Customer or EASA spec(<10%

No

## Conclusion

Service Tech name: **BILLY MAYS** 

Service Tech signature: