

Job Information

Job #:	138134				Date:	October 3, 2018
Priority:	-	Authorized OT:	No	Authorized by:		

Customer Information

Name:	FORTERRA	Motor#:

Name Plate Information

DEMAG	Enclosure :	Totally Enclosed Fan Cooled	Horsepower/kW:	46
41652108	Model#:	KBH200B	Service Factor:	N/A
IMB14	Rated RPM:	1155	Rated Voltage:	460
3	Rated Amps:	71	Cycles:	60
	41652108 IMB14	41652108 Model#: IMB14 Rated RPM:	Fan Cooled 41652108 Model#: KBH200B IMB14 Rated RPM: 1155	Fan Cooled41652108Model#:KBH200BService Factor:IMB14Rated RPM:1155Rated Voltage:

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition:	Good	Bearings Retainer:	Yes
Type of grounding device:		Bearing DE Size:	6310
Shaft runout(TIR-Inbound):	.001	Bearing ODE Size:	6310
Retainer condition:	Good		

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Mechanical Inspection (Continued)

Seals DE condition :	Worn	Brg. Seats DE:	Good
Seals DE type:	Slinger	If DE undersized, amt.:	.000
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	.000
Seals ODE condition :	Worn	Shaft damage:	ОК
Seals ODE type:	Slinger		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	4.331	Foot flatness:	Pass
Endbell DE insulated?:	No	Doos Air Gan Moot Cus	tomer or EASA spec(<10%
Endbell ODE size:	4.331	variation)?	
Endbell ODE insulated?:	No	Yes	

Conclusion

Service Tech name: BILLY MAYS

Service Tech signature:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254