

#### **Job Information**

Job #: 96703 Date: April 7, 2020

Priority: — Authorized OT: No Authorized by:

**Customer Information** 

Name: 3M Motor#:

**Name Plate Information** 

Manufacturer: R&K Hoist Enclosure: Open Drop Proof Horsepower/kW: 60

(ODP)

Serial#: 119027-18A-1163 Model#: Service Factor:

Frame: HEW505 Rated RPM: 875 Rated Voltage: 440

Phase: 3 Rated Amps: 81 Cycles: 60

Special design: No

**AC Electrical Inspection** 

Megs after rewind: Good Surge after rewind: Good Hi-pot after rewind: Good

Core loss: Good Thermistors: None Thermostat: None

RTD: None ohms at degrees C

Motor Heater(s) Present: Yes Qty: Voltage: Wattage:



## **AC Electrical Inspection (Continued)**

#### **Core Test Data**

Condition of iron Flux Watts Watts loss per lb

Before burnout

After burnout 85.116 0.503 1.601 318

#### Conclusion

Service Tech name: **RHR** 

Service Tech signature:

Fax 901-873-5301

April 7, 2020

Polyphase Date:



<b>Polyphase</b>	AC	Win	ding
------------------	----	-----	------

8 Manufacturer: Hp/kw: 60 RPM: 875 Poles: **R&K Hoist** 

Slots: 72 Volts: 440 Type:

Coils: 72 Model: Amps: 81

24 Of 3 Serial#: 119027-18A-1163 Phase: 3

Grouping Lead marking: Hertz: 60 Of

9 Turns/Coil: Lead length: 16 C Rise: Frame: **HEW505** 

Wire Size Lead size: C AMB: 15 2 Duty:

Wire Mult. 4 Num.Leads: 3 Eff.: Ins.Cls.:

8 □ DP TEFC XPRF TENV Pitch 1 to: S.F.:

2D

Core length: 9.5

Connection:

Jumper:

Core ID: 15.5

Back iron: 1.25


Slot depth: 1.375

Slot/tooth w: 0.284

Wire weight: 84

Vents: Size

Rotor bars:







Single Phase				-		: Phas			art	Г	⊐ sta	art & R	un		Perm.	Split		
Hp/kw:	60			RPM:		75				facture		R&K I			•	<b>о</b> р•		
		Run		Start			Type:							٧	olts:	440		
No. Slots	s					1	Model: Style:								mps: ertz:	81		
No. Poles	S						Form:								ame:			
Coils/pole	Э																	
Dwg No							C Ris	se:			Hrs.:			Ca	ap. Mf	d.:		
Wire Size	Э		Serial#: 119027-18A-1163															
Wires in par	:						Du	ty: -	_						3B		SB	
No. Circuits	S			Open: —														
Coil Ext				Sta.length:						Sta.b.i.:								
Stator Bore	€																	
			l															
Running																		
Slot No	. 1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
Startino	g 🔲																	
Customer	: 3	BM																

(Please return a copy to EASA Headquarters, 1331 Baur Blvd., St. Louis, MO 63132)



### **AC Stator Form Coil Data**

- 1. Core bore diameter
- 2. Total core length
- 3. Back iron
- 4. No. of vents
- 5. Width of vents
- 6. Finger plate width
- 7. Overall coil length
- 8. Connnection end extension
- 9. Opposite Conn. End Ext.
- 10. Straight length bottom side
- 11. Straight length top side
- 12. Small knuckle drop. CE

OCE

13. Large knuckle drop. CE

OCE

- 14. Conn. Support Ring from core
- 15. Opp. Conn. Supp. Ring from core
- 16. Connection support ring ID
- 17. Opp. Conn. Supp. Ring ID
- 18. Total slot depth
- 19. Slot depth under wedge
- 20. Slot width











CENTRAL ARKANSAS



# **AC Stator Form Coil Data (Continued)**

21. Lead location A B C D

23. Coil leads Long# LG

Short# LG

Out Down

24. Jumper —

25. Connection —

26. No. of circuits

27. No. of slots

28. Coil throw

29. Turns per coil

30. Total wires in parallel

31. Bare wire sizes ( ) x

( ) x

32. Strand insulation

☐ Film ☐ Glass ☐ Mica ☐ Bare ☐ Other


33. Coil weight Lbs.


34. Groups of Coils

Groups of Coils

35. Iron skewed Right Left in











# **AC Stator Form Coil Data (Continued)**

Special Features	Yes	No					
Data change							
Coil support ring steel							
Terrace wound							
Corona Protection							
RTDs							
Ohms Qty							
Hermetic							
Slot paper used							
Insulation class B B H							
☐ VPI ☐ Dip & Bake ☐ Sealed							
Leads taped Leads sleeved							
Comments							

