

LR Field Services

Prepared for Midsouth Steam Boiler

3805 Pointer Trail East
Van Buren AR 72956

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Balancing Report

FolderID: 100386
FormID: 14741133

Midsouth Steam Boiler
3805 Pointer Trail East
Van Buren, AR 72956
Hilmar Cheese Company



Performed By: Motor Shop LR 1

General

1. Job Number	100386
2. Report Date	10/05/2022
3. Customer	Hilmar/ MSSB

Balancing Report

4. Balance Type	single weight plane overhung
5. Balance Operating Speed	3586 RPM
6. Starting Measurements	
Left End	Right End
1.3072	1.2543
7. Balancing Specification	1.0
8. Finished Measurements	
Left End	Right End
0.5931	0.414



9. List Parts Needed
2 - 7g clamp weights

10. Service Technician

David Maclin

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 10/05/2022

Powered by INSPECTALL

1.0