



8/26/2021 7:42:57 AM



IR_1940.jpg S60 NTSC 21801575

8/26/2021 7:43:08 AM



DC_1941.jpg

Measurements

Sp1	123.1 °F
Sp2	126.5 °F
Sp3	122.9 °F

Parameters

Emissivity	0.95
Refl. temp.	49 °F

Infrared data indicates that All 3 fuses is operating at higher than normal temperatures. Replace all 3 fuses and clean fuse holders.