



8/25/2021 5:38:10 AM



IR_1919.jpg S60 NTSC 21801575

8/25/2021 5:38:21 AM



DC_1920.jpg

Measurements

Sp1	103.3 °F
Sp2	102.6 °F
Sp3	91.7 °F

Parameters

Emissivity	0.95
Refl. temp.	49 °F

Infrared data indicates that phase B and C is operating 10* higher . Clean fuse holders and replace all 3 fuses.