



8/25/2021 5:33:02 AM



IR_1917.jpg S60 NTSC 21801575

8/25/2021 5:33:27 AM



DC_1918.jpg

Measurements

Sp1	148.5 °F
Sp2	124.0 °F
Sp3	111.2 °F

Parameters

Emissivity	0.95
Refl. temp.	49 °F

Phase B is operating 20* higher than Phases A and C. Clean fuse clips and replace all 3 fuses.