LR Field Services

Prepared for Almatis Inc/RCP Bauxite (10014)

4701 Alcoa Road Bauxite AR 72011

Table of Contents

| Field Service Ticket | 1.0 |
|----------------------|-----|
| Field Service Ticket | 2.0 |

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

> FolderID: 102625 FormID: 19716459

Field Service Ticket

Almatis Inc/RCP Bauxite (10014) 4701 Alcoa Road Bauxite, AR 72011 Performed By: Will Reaves Date Completed: 03/11/2024

| Job In | formation |
|--------|---|
| 1. | Hi-Speed Job Number 102625 |
| 2. | Asset Type |
| 3. | Make |
| 4. | Model |
| 5. | Serial Number |
| 6. | Customer Asset ID/Asset Name |
| Servic | e Call Details |
| 7. | Service Objectives |
| | Monthly vibration survey |
| 8. | Services Performed |
| | Took vibration data on all running route equipment. |
| 9. | Service Technician Recommendations |
| | Recommendations will be on report |
| Appro | val Signatures |
| 10. | Service Technician Signature |
| 11. | Customer Signature A S A S A S A S A S A S A S A S A S A |



Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

> FolderID: 102625 FormID: 19733389

Field Service Ticket

Almatis Inc/RCP Bauxite (10014) 4701 Alcoa Road

Bauxite, AR 72011

Performed By: Will Reaves Date Completed: 03/12/2024

| Job In | Job Information | | | |
|----------------------|---|-------------|--|--|
| 1. | Hi-Speed Job Number | 102625 | | |
| 2. | Asset Type | | | |
| 3. | Make | | | |
| 4. | Model | | | |
| 5. | Serial Number | | | |
| 6. | Customer Asset ID/Asset Name | | | |
| Service Call Details | | | | |
| 7. | Service Objectives | | | |
| | Monthly oil analysis | | | |
| 8. | Services Performed | | | |
| | Gathered 21 oil samples to be sent off for analysis | | | |
| 9. | Service Technician Recommendations | | | |
| | Recommendations will be on report | | | |
| Approval Signatures | | | | |
| 10. | Service Technician Signature | | | |
| 11. | Customer Signature | David Wolfe | | |
| 4 |) - 1 E Wallu | | | |