



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300



**Asset Type:** AC Inspection - Rev. 2

**Account:** Welspun Tubular (11685)

**Location:** LR MOTORSHOP

**Serial Number:** C0712110100

**Date:** 4/19/2024

**Description:** 110KW 1780 RPM



Serial Number

#### Attributes

**Hi-Speed Job Number:** 102812

**Manufacturer:** Baldor

**Product Number:** 18M092X600H2

**Serial Number:** C0712110100

**HP/kW:** 110 (kW)

**RPM:** 1780 (RPM)

**Frame:** D315S

**Voltage:** 230 / 460

**Current:** 340/170 (Amps)

**Phase:** Three

**Hz:** 60 (Hz)

**Service Factor:** 1.00

**Enclosure:** TEFC

**# of Leads:** 9

**J-box Included:** None

**Coupling/Sheave:** None

**Date Received:** 04/24/2024

**Bearing RTDs:** No

**Stator RTDs:** No

**Repair Stage:** Teardown Inspection

**Rewind:** Yes

**Shaft Machined Fit Repairs Required:** No

**Bearing Housing Machined Fit Repairs Required:** Yes

**Heaters:** No

**Winding Type :** Random Wound

**Bearing Type:** Rolling Element

This asset has no forms completed for it yet.

