



Field Service Ticket

FolderID: 102599
FormID: 20722468

LITTLE ROCK ZOO
1 ZOO DRIVE
LITTLE ROCK, AR 72205

Job Information



- | | |
|------------------------|--------|
| 1. Hi-Speed Job Number | 103113 |
| 2. Asset Type | Pump |
| 3. Make | P3 |



- | | |
|---------------------------------|--------------|
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | Penguin pump |

Service Call Details



- | | |
|---|----|
| 7. Service Objectives | |
| <i>Install rebuilt pump</i> | |
| 8. Services Performed | P8 |
| <i>Installed pump. Test ran pump. Motor pulls 5 amps all 3 legs. Voltage is 209, 209 and 210.</i> | |



- | | |
|---------------------------------------|--|
| 9. Service Technician Recommendations | |
|---------------------------------------|--|

Approval Signatures

- | | |
|----------------------------------|-------------|
| 10. Service Technician Signature | Trevor Hall |
|----------------------------------|-------------|

11. Customer Signature

Colden Dostal

A handwritten signature in black ink, appearing to read 'Colden Dostal', is written over a light gray grid background.