



## Field Service Ticket

FolderID: 103518  
FormID: 21670723

**ConAgra (10859-CON)**  
3100 E. Main St.  
Russellville, AR 72801

### Job Information



- |                        |            |
|------------------------|------------|
| 1. Hi-Speed Job Number | 103518     |
| 2. Asset Type          | Compressor |
| 3. Make                | P3         |




- |                                 |               |
|---------------------------------|---------------|
| 4. Model                        |               |
| 5. Serial Number                |               |
| 6. Customer Asset ID/Asset Name | B4 compressor |

### Service Call Details



- |   |    |
|---|----|
| 7. Service Objectives   |    |
| <i>Align motor to compressor</i>  |    |
| 8. Services Performed   | P8 |
| <i>Laser aligned motor to compressor. Started at two mils out at the coupling, ended at 0. Good. Alignment took away the vibration of the compressor. Customer was happy.</i> |    |



- |                                       |  |
|---------------------------------------|--|
| 9. Service Technician Recommendations |  |
|---------------------------------------|--|

### Approval Signatures

- |                                  |             |
|----------------------------------|-------------|
| 10. Service Technician Signature | Trevor Hall |
|----------------------------------|-------------|

A handwritten signature in black ink, appearing to read 'Edward White', is written within a rectangular box.