



## Field Service Ticket

FolderID: 103549  
FormID: 21733499

**Murray Hydro Plant (10772-MHP)**  
8th St. & Main St.  
N.Little Rock, AR 72115

### Job Information

1. Hi-Speed Job Number	103549
2. Asset Type	Generator
3. Make	
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	Unit 2

### Service Call Details




7. Service Objectives




*Perform PDMA on unit 2*

8. Services Performed

*Performed PDMA on unit 2. Checked the rotor and the stator separately. Brushes looked good so we did not touch them.*

P8







9. Service Technician Recommendations

*Unit is getting very dirty inside and covered in carbon. Unit is going to need to be cleaned at some point. Maybe dry ice blast.*

**Approval Signatures**

10. Service Technician Signature

**Thomas Hankins**

11. Customer Signature

**Trevor Hall**