



## Field Service Ticket

FolderID: 103869  
FormID: 22584361

**3M-Main Plant (10001) / CBRE (12815)**

3100 Walter Road  
Little Rock, AR 72216

### Job Information



- |                        |               |
|------------------------|---------------|
| 1. Hi-Speed Job Number | 103869        |
| 2. Asset Type          | Crusher motor |
| 3. Make                | P3            |



- |                                 |             |
|---------------------------------|-------------|
| 4. Model                        |             |
| 5. Serial Number                |             |
| 6. Customer Asset ID/Asset Name | New Crusher |

### Service Call Details



- |   |    |
|---|----|
| 7. Service Objectives                       |    |
| <i>Laser align new motor to new crusher</i> |    |
| 8. Services Performed                       | P8 |
| <i>Aligned motor to crusher.</i>            |    |



- |                                       |  |
|---------------------------------------|--|
| 9. Service Technician Recommendations |  |
|---------------------------------------|--|

### Approval Signatures

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

10. Service Technician Signature

**Trevor Hall**

A handwritten signature in black ink, appearing to be 'T. Hall', written in a cursive style.

11. Customer Signature

**Chase Crissup**

A handwritten signature in black ink, appearing to be 'Chase Crissup', written in a cursive style.