

LR Field Services

Prepared for Almatris Inc/RCP Bauxite (10014)

4701 Alcoa Road
Bauxite AR 72011

Table of Contents

Field Service Ticket	1.0
Field Service Ticket	2.0



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

Almatis Inc/RCP Bauxite (10014)
4701 Alcoa Road
Bauxite, AR 72011

FolderID: 104299
FormID: 23851809

Job Information

- | | |
|---------------------------------|--|
| 1. Hi-Speed Job Number | 104299 |
| 2. Asset Type | multiple pieces of equipment.
3/25/25 |
| 3. Make | |
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | |

Service Call Details

- | | |
|---------------------------------------|---|
| 7. Service Objectives | Monthly vibration |
| 8. Services Performed | Took monthly vibration data and oil samples |
| 9. Service Technician Recommendations | |

Approval Signatures

- | | |
|----------------------------------|-------------|
| 10. Service Technician Signature | Trevor Hall |
|----------------------------------|-------------|

- | | |
|------------------------|-------------|
| 11. Customer Signature | David Wolfe |
|------------------------|-------------|



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104299
FormID: 23870994

Almatis Inc/RCP Bauxite (10014)
4701 Alcoa Road
Bauxite, AR 72011

Job Information

- | | |
|---------------------------------|---|
| 1. Hi-Speed Job Number | 104299 |
| 2. Asset Type | Multiple pieces of equipment
3/24/25 |
| 3. Make | |
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | |

Service Call Details

- | |
|---|
| 7. Service Objectives |
| Take monthly vibration data and oil samples |
| 8. Services Performed |
| Took vibration data. |
| 9. Service Technician Recommendations |

Approval Signatures

- | | |
|----------------------------------|-------------|
| 10. Service Technician Signature | Trevor Hall |
|----------------------------------|-------------|

- | | |
|------------------------|--------------------------|
| 11. Customer Signature | Nobody Was In The Office |
|------------------------|--------------------------|