

# LR Field Services

Prepared for ARKANSAS INDUSTRIAL MACHINERY

3804 N. NONA ST  
NORTH LITTLE ROCK AR 72118

# Table of Contents

Field Service Ticket

1.0

---

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 05/30/2025

Powered by [INSPECTALL](#)

*Table of Contents*



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## Field Service Ticket

FolderID: 104682  
FormID: 24629749




ARKANSAS INDUSTRIAL  
MACHINERY  
3804 N. NONA ST  
NORTH LITTLE ROCK, AR 72118

### Job Information

- |   |                            |
|---|----------------------------|
| 1. Hi-Speed Job Number                      | 104682                     |
| 2. Asset Type                               | atlas copco air compressor |
| 3. Make                                     | 75 kw motor.               |
| Could not read information on the nameplate |                            |
| 4. Model                                    |                            |
| 5. Serial Number                            |                            |
| 6. Customer Asset ID/Asset Name             |                            |

### Service Call Details

7. Service Objectives  
*To check motor*
8. Services Performed  
*I megged the motor and the motor has 1300 megaohms. I then used the Baker surge tester and one phase shows to be good but the other two phases show to be shorted together. The motor is shorted and needs to be rewound.*



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



9. Service Technician Recommendations

*Pull motor for further evaluation.*

**Approval Signatures**

10. Service Technician Signature

**Trevor Hall**

11. Customer Signature

**Beavor Smith**