



## Field Service Ticket

FolderID: 104065  
FormID: 23285622

**Almatis Inc/RCP Bauxite (10014)**

4701 Alcoa Road  
Bauxite, AR 72011

### Job Information



- |                        |        |
|------------------------|--------|
| 1. Hi-Speed Job Number | 104065 |
| 2. Asset Type          | P2     |



- |                                 |         |
|---------------------------------|---------|
| 3. Make                         |         |
| 4. Model                        |         |
| 5. Serial Number                |         |
| 6. Customer Asset ID/Asset Name | T2-Mill |

### Service Call Details

- |   |
|---|
| 7. Service Objectives                                   |
| <i>Feeler gauge to adjust clearance in clutch brake</i> |
| 8. Services Performed                                   |
| <i>Set clearance</i>                                    |
| 9. Service Technician Recommendations                   |

### Approval Signatures

- |                                  |            |
|----------------------------------|------------|
| 10. Service Technician Signature | Shon Jones |
|----------------------------------|------------|

- |                        |                 |
|------------------------|-----------------|
| 11. Customer Signature | Zachary Creasey |
|------------------------|-----------------|