



Field Service Ticket

West Fraser Mills (10728-01)
1400 Main Street
Leola, AR 72084

FolderID: 104210
FormID: 23558573

Job Information



1. Hi-Speed Job Number **104210**
2. Asset Type
3. Make
4. Model
5. Serial Number
6. Customer Asset ID/Asset Name

P6



Service Call Details



7. Service Objectives
8. Services Performed

P8



9. Service Technician Recommendations

P9

Front left foot pad weld broken, re-weld foot pad. Front right foot bolt broken off in base. Extract broken bolt.slot hole in back left foot for alignment.



Approval Signatures

10. Service Technician Signature

11. Customer Signature

Charles Roquemoire

A handwritten signature in black ink, appearing to read 'Charles Roquemoire', written on a white background.