

LR Field Services

Prepared for Hi-Speed Industrial Service - 2

7030 Ryburn Dr
Millington TN 38053

Table of Contents

Balancing Report	1.0
Field Service Ticket	2.0



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Balancing Report

Hi-Speed Industrial Service - 2
7030 Ryburn Dr
Millington, TN 38053

Performed By: Shon Jones
Date Completed: 03/21/2025

FolderID: 104326
FormID: 23806443

General

1. Job Number	104326
2. Report Date	03/20/2025
3. Customer	Nucor Memphis

Balancing Report

4. Balance Type	single plane-dynamic
5. Balance Operating Speed	893 RPM



6. Starting Measurements

Left End	Right End
0.7	9.4



7. Balancing Specification	1.0
----------------------------	-----

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

8. Finished Measurements

Left End

0.02

Right End

0.8



9. List Parts Needed

10. Service Technician

Shon Jones



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

Hi-Speed Industrial Service - 2
7030 Ryburn Dr
Millington, TN 38053

Performed By: Shon Jones
Date Completed: 03/21/2025

FolderID: 104326
FormID: 23815113

Job Information

1. Hi-Speed Job Number **104326**
2. Asset Type



3. Make
4. Model
5. Serial Number
6. Customer Asset ID/Asset Name **main bag house fan #4**

Service Call Details

7. Service Objectives
Balance fan, check vibration. Provide report
8. Services Performed
Balance on main bag house fan
9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature **Shon Jones**

11. Customer Signature **Kevin Franklin**