


8/26/2021 10:46:34 AM



IR_1950.jpg S60 NTSC 21801575

8/26/2021 10:46:45 AM



DC_1951.jpg

Measurements

Sp1	133.6 °F
-----	----------

Parameters

Emissivity	0.95
Refl. temp.	49 °F

Infrared data indicates that the Main breaker is operating 15* higher than the rest of the panel. Check load and reduce if necessary. Replace breaker if necessary NOT to exceed the electrical panel rating load.