

Job Information

Job #:	135418				Date:	February 8, 2018
Priority:	-	Authorized OT:	No	Authorized by:	Terry f	

Customer Information

Name: Ktg 4 Motor#:

Name Plate Information

Manufacturer:	ABB	Enclosure :	Open Drop Proof (ODP)	Horsepower/kW:	246
Serial#:		Model#:		Service Factor:	
Frame:		Rated RPM:	1184	Rated Voltage:	460
Phase:	3	Rated Amps:	120	Cycles:	

Special design: No

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection

Megs at reassem	nbly: Good	Surge at reassem	bly: Good	Hi-pot reassembly: Good		
Winding Resistance Incoming						
	Phases A to B	Phases B to C	Phases C to	A Resistive imbalance		
Outgoing	0.010	0.010	0.010	0.6		
Test Run Inspection Date February 8, 2018						
— I have merged this motor and verified that all electrical tests are complete!						
Power Supp	ly	Phase A	Phase B	Phase C		
No Load Voltage						
No Load Cur	rent					
Temperatures: (Degrees Fahrenheit)						
Test run ball-bearing motors for 15 minutes.						

Test run sleeve bearing motors for 60 minutes.

Temperature rise at the end of test run should be less than 2° every five minutes.

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

Test Run Inspection (Continued)

Ambient Temp:	63			
TIME	DE	Degree Change	ODE	Degree Change
START:	63	1	64	
5 MIN:	66	2	68	
10 MIN:	68	4	72	
15 MIN:	75	2	73	
20 MIN:				
25 MIN:				
30 MIN:				
35 MIN:				
40 MIN:				
45 MIN:				
50 MIN:				
55 MIN:				
60 MIN:				

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Test Run Inspection (Continued)

Vibration Data: In./Sec-Peak	(Readings should be less than .08 In/Sec Peak)			
	Horizontal	VDE	Axial	
DE	0.017	0.017	0.017	
ODE	0.019	0.020	0.020	

Magnetic Center Measurements (Only Applies to Sleeve Bearing Motors)

Magnetic Center line distance from shaft shoulder

Magnetic Center line distance from all the way out mark

Magnetic Center line distance from all the way in mark

Total Motor End Float

Additional photos









Yes, the shaft has been isolated for delivery.

Service Tech name: Te

Terry f

Service Tech signature:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301