

Job Information

Job #:	140238				Date:	November 18, 2019
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	HSLR	Motor#:	140238

Name Plate Information

Manufacturer:	Kenzie	Enclosure :	Totally Enclosed Fan Cooled	Horsepower/kW:	9.25
Serial#:	15553246 10000 176132051	Model#:		Service Factor:	
Frame:		Rated RPM:	3480	Rated Voltage:	390
Phase:	3	Rated Amps:	15.8	Cycles:	120

Special design: No

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Date

November 18, 2019

AC Electrical Inspection

Megs at reassem	bly: Good	Surge at reassembly:	Good	Hi-pot reassembly:	Good
Winding Resista	nce Incoming				
	Phases A to E	B Phases B to C	Phases C to A	Resistive imbala	ance
Outgoing	0.786000	0.787700	0.786800	0.2	

Test Run Inspection

Yes I have merged this motor and verified that all electrical tests are complete!

Power Supply

	Phase A	Phase B	Phase C
No Load Voltage	230	230	230
No Load Current	15.8	15.8	15.8

Temperatures: (Degrees Fahrenheit)

Test run ball-bearing motors for 15 minutes.

Test run sleeve bearing motors for 60 minutes.

Temperature rise at the end of test run should be less than 2° every five minutes.

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Test Run Inspection (Continued)

Ambient Temp:

TIME	DE	Degree Change	ODE	Degree Change
START:	67	0	67	0
5 MIN:	69	2	68	1
10 MIN:	71	2	69	1
15 MIN:	72	1	69	0
20 MIN:				
25 MIN:				
30 MIN:				
35 MIN:				
40 MIN:				
45 MIN:				
50 MIN:				
55 MIN:				
60 MIN:				



Test Run Inspection (Continued)

Vibration Data: In./Sec-Peak	(Readings should be less than .08 In/Sec Peak)		
	Horizontal	VDE	Axial
DE	0.030	0.033	0.028
ODE	0.038	0.013	0.028

Magnetic Center Measurements (Only Applies to Sleeve Bearing Motors)

Magnetic Center line distance from shaft shoulder

Magnetic Center line distance from all the way out mark

Magnetic Center line distance from all the way in mark

Total Motor End Float

Additional photos









Yes, the shaft has been isolated for delivery.

Service Tech name:

Shawn

Service Tech signature:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301