



MILLINGTON, TN

LITTLE ROCK, AR

## Job Information

Job #: 142664

Date: June 23, 2020

Priority: —

Authorized OT: No

Authorized by:

## Customer Information

Name: KTG

Motor#: 142664

## Name Plate Information

Manufacturer: Mario cotta

Enclosure : Open Drop Proof  
(ODP)

Horsepower/kW: .45 KW

Serial#: F381/08

Model#:

Service Factor: S1

Frame:

Rated RPM: 1590

Rated Voltage: 380

Phase: 3

Rated Amps: 1,3

Cycles:

Special design: No

### WEST TENNESSEE

7030 Ryburn Drive  
Millington, TN 38053  
Phone 901-873-5300  
Fax 901-873-5301

### CENTRAL ARKANSAS

6812 Lindsey Rd.  
Little Rock, AR 72206  
Phone 501-375-9178  
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

## AC Electrical Inspection

Megs at reassembly: Good

Surge at reassembly: Good

Hi-pot reassembly: Good

### Winding Resistance Incoming

Phases A to B

Phases B to C

Phases C to A

Resistive imbalance

Outgoing

## Test Run Inspection

Date June 23, 2020

— I have merged this motor and verified that all electrical tests are complete!

### Power Supply

|                 | Phase A | Phase B | Phase C |
|-----------------|---------|---------|---------|
| No Load Voltage | 249.    | 250.    | 250.    |
| No Load Current | 1.1     | 1.4     | 1.3     |

### Temperatures: (Degrees Fahrenheit)

**Test run ball-bearing motors for 15 minutes.**

**Test run sleeve bearing motors for 60 minutes.**

Temperature rise at the end of test run should be less than 2° every five minutes.

**WEST TENNESSEE**  
7030 Ryburn Drive  
Millington, TN 38053  
Phone 901-873-5300  
Fax 901-873-5301

**CENTRAL ARKANSAS**  
6812 Lindsey Rd.  
Little Rock, AR 72206  
Phone 501-375-9178  
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

## Test Run Inspection (Continued)

**Ambient Temp:** 75

| TIME | DE | Degree Change | ODE | Degree Change |
|------|----|---------------|-----|---------------|
|------|----|---------------|-----|---------------|

|        |    |   |    |   |
|--------|----|---|----|---|
| START: | 75 | 0 | 75 | 0 |
|--------|----|---|----|---|

5 MIN:

10 MIN:

|         |    |   |    |   |
|---------|----|---|----|---|
| 15 MIN: | 75 | 0 | 75 | 0 |
|---------|----|---|----|---|

20 MIN:

25 MIN:

30 MIN:

35 MIN:

40 MIN:

45 MIN:

50 MIN:

55 MIN:

60 MIN:

### WEST TENNESSEE

7030 Ryburn Drive  
Millington, TN 38053  
Phone 901-873-5300  
Fax 901-873-5301

### CENTRAL ARKANSAS

6812 Lindsey Rd.  
Little Rock, AR 72206  
Phone 501-375-9178  
Fax 501-375-4254

## Test Run Inspection (Continued)

Vibration Data: In./Sec-Peak (Readings should be less than .08 In/Sec Peak)

Horizontal

VDE

Axial

DE

ODE

## Magnetic Center Measurements (Only Applies to Sleeve Bearing Motors)

Magnetic Center line distance from shaft shoulder

Magnetic Center line distance from all the way out mark

Magnetic Center line distance from all the way in mark

Total Motor End Float

## Additional photos



☐ Yes, the shaft has been isolated for delivery.

Service Tech name: Jesus

Service Tech signature:

