

Job Information

Job #:	94161				Date:	May 15, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:Entergy White BluffMotor#:

Name Plate Information

Westinghouse	Enclosure :	Open Drop Proof (ODP)	Horsepower/kW:	1.1
7903	Model#:	ТВАН	Service Factor:	1.0
213TZ	Rated RPM:	900	Rated Voltage:	460
3	Rated Amps:	2.3	Cycles:	60
	7903 213TZ	7903 Model#: 213TZ Rated RPM:	YesYesYes7903Model#:TBAH213TZRated RPM:900	YesYesYesYes7903Model#:TBAHService Factor:213TZRated RPM:900Rated Voltage:

Special design: No

VUEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection

Megs at reassem	oly: Good	Surge at reassembly	: Good	Hi-pot reassembly: Good			
Winding Resistance Incoming							
	Phases A to B	Phases B to C	Phases C to A	Resistive imbalance			
Outgoing	20.747	20.784	20.769	0.2			
Test Run InspectionDateMay 15, 2018							
— I have merged this motor and verified that all electrical tests are complete!							
Power Supply							
		Phase A Pl	hase B	Phase C			

	Phase A	Phase B	Phase C
No Load Voltage	460	459	460
No Load Current	1.5	1.6	1.6

Temperatures: (Degrees Fahrenheit)

Test run ball-bearing motors for 15 minutes.

Test run sleeve bearing motors for 60 minutes.

Temperature rise at the end of test run should be less than 2° every five minutes.

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR


Test Run Inspection (Continued)

Ambient Temp:

TIME	DE	Degree Change	ODE	Degree Change
START:				
5 MIN:				
10 MIN:				
15 MIN:				
20 MIN:				
25 MIN:				
30 MIN:				
35 MIN:				
40 MIN:				
45 MIN:				
50 MIN:				
55 MIN:				
60 MIN:				



Test Run Inspection (Continued)



Total Motor End Float

Additional photos









Yes, the shaft has been isolated for delivery.

Service Tech name:

RHR

Service Tech signature:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301