

Job Information

| Job #: | 94369 | | | | Date: | July 6, 2018 |
|-----------|-------|----------------|----|----------------|-------|--------------|
| Priority: | _ | Authorized OT: | No | Authorized by: | | |

Customer Information

Name: Flakeboard Motor#:

Name Plate Information

| Manufacturer: | Reliance | Enclosure : | Open Drop Proof (ODP) | Horsepower/kW: | 100 |
|---------------|-------------|-------------|--------------------------|-----------------|------|
| Serial#: | 1NA46069762 | Model#: | | Service Factor: | 1.15 |
| Frame: | 404TS | Rated RPM: | 1770 | Rated Voltage: | 460 |
| Phase: | 3 | Rated Amps: | 120 | Cycles: | 60 |

Special design: No

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection

| Megs at reassem | oly: Good | Surge at reassem | bly: Good | Hi-pot reassembly: Goo | bd | |
|---|---------------|------------------|-------------|------------------------|----|--|
| Winding Resistance Incoming | | | | | | |
| | Phases A to B | Phases B to C | Phases C to | A Resistive imbalance | | |
| Outgoing | 0.114 | 0.124 | 0.112 | 8.5 | | |
| Test Run Inspection Date July 6, 2018 | | | | | | |
| — I have merged this motor and verified that all electrical tests are complete! | | | | | | |
| Power Supply | | | | | | |
| | | Phase A | Phase B | Phase C | | |
| No Load Volta | ige | 460 | 458 | 460 | | |
| No Load Curr | ent | 40.5 | 41.0 | 39.9 | | |

Temperatures: (Degrees Fahrenheit)

Test run ball-bearing motors for 15 minutes.

Test run sleeve bearing motors for 60 minutes.

Temperature rise at the end of test run should be less than 2° every five minutes.

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

Test Run Inspection (Continued)

Ambient Temp:

| TIME | DE | Degree Change | ODE | Degree Change |
|---------|----|---------------|-----|---------------|
| START: | | | | |
| 5 MIN: | | | | |
| 10 MIN: | | | | |
| 15 MIN: | | | | |
| 20 MIN: | | | | |
| 25 MIN: | | | | |
| 30 MIN: | | | | |
| 35 MIN: | | | | |
| 40 MIN: | | | | |
| 45 MIN: | | | | |
| 50 MIN: | | | | |
| 55 MIN: | | | | |
| 60 MIN: | | | | |



Test Run Inspection (Continued)

| Vibration Data: In./Sec-Peak | (Readings should be less than .08 In/Sec Peak) | | | |
|------------------------------|--|------|-------|--|
| | Horizontal | VDE | Axial | |
| DE | 0.08 | 0.05 | 0.06 | |
| ODE | 0.08 | 0.05 | 0.05 | |

Magnetic Center Measurements (Only Applies to Sleeve Bearing Motors)

Magnetic Center line distance from shaft shoulder

Magnetic Center line distance from all the way out mark

Magnetic Center line distance from all the way in mark

Total Motor End Float

Additional photos









Yes, the shaft has been isolated for delivery.

Service Tech name:

Lynn McDonald

Service Tech signature:

Lynn McDould

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301