

Job Information

Job #:	94493				Date:	July 18, 2018
Priority:	-	Authorized OT:	No	Authorized by:		

Customer Information

Name: Durwood Motor#:

Name Plate Information

Manufacturer:	BALDOR	Enclosure :	Totally Enclosed Fan Cooled	Horsepower/kW:	250
Serial#:		Model#:		Service Factor:	
Frame:		Rated RPM:		Rated Voltage:	
Phase:		Rated Amps:		Cycles:	

Special design: No

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection

Megs at reassem	bly: Good	Surge at reassembly:	Good	Hi-pot reassembly: Good
Winding Resista	nce Incoming			
	Phases A to B	Phases B to C	Phases C to A	Resistive imbalance
Outgoing	11.334	11.340	11.249	0.7
Test Run I	Inspection		Date	July 18, 2018
Yes	I have merged this motor and verified that all electrical tests are complete!			

Power Supply

	Phase A	Phase B	Phase C
No Load Voltage	455	455	454
No Load Current	86.9	86.1	85.3

Temperatures: (Degrees Fahrenheit)

Test run ball-bearing motors for 15 minutes.

Test run sleeve bearing motors for 60 minutes.

Temperature rise at the end of test run should be less than 2° every five minutes.

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

Test Run Inspection (Continued)

Ambient Temp:

TIME	DE	Degree Change	ODE	Degree Change
START:				
5 MIN:				
10 MIN:				
15 MIN:				
20 MIN:				
25 MIN:				
30 MIN:				
35 MIN:				
40 MIN:				
45 MIN:				
50 MIN:				
55 MIN:				
60 MIN:				



Test Run Inspection (Continued)

Vibration Data: In./Sec-Peak	(Readings should be le	ess than .08 In/Sec Peal	()
	Horizontal	VDE	Axial
DE	0.00	0.00	0.00
ODE	0.07	0.06	0.00

Magnetic Center Measurements (Only Applies to Sleeve Bearing Motors)

Magnetic Center line distance from shaft shoulder

Magnetic Center line distance from all the way out mark

Magnetic Center line distance from all the way in mark

Total Motor End Float

Additional photos









Yes, the shaft has been isolated for delivery.

Service Tech name:

Robert Wiley

Service Tech signature:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301