

Job Information

Job #:	97004				Date:	July 7, 2020
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Motor#:

Name Plate Information

Manufacturer:	US	Enclosure :	Open Drop Proof (ODP)	Horsepower/kW:	350
Serial#:		Model#:	DS06	Service Factor:	1.15
Frame:	447TPA	Rated RPM:	1785	Rated Voltage:	460
Phase:	3	Rated Amps:	389	Cycles:	60

Special design: No

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection

Megs at reassemb	oly: Good	Surge at reassemb	ly: Good	Hi-pot reassembly: Good				
Winding Resistance Incoming								
	Phases A to B	Phases B to C	Phases C to	A Resistive imbalance				
Outgoing	0.00	0.00	0.00	0.00				
Test Run InspectionDateJuly 7, 2020								
Yes I have merged this motor and verified that all electrical tests are complete!								
Power Supply	y	Phase A	Phase B	Phase C				
No Load Volta	ge	457	455	457				

No Load Current 8	35.9	84.3	84.8

Temperatures: (Degrees Fahrenheit)

Test run ball-bearing motors for 15 minutes.

Test run sleeve bearing motors for 60 minutes.

Temperature rise at the end of test run should be less than 2° every five minutes.

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

Test Run Inspection (Continued)

Ambient Temp:

TIME	DE	Degree Change	ODE	Degree Change
START:				
5 MIN:				
10 MIN:				
15 MIN:				
20 MIN:				
25 MIN:				
30 MIN:				
35 MIN:				
40 MIN:				
45 MIN:				
50 MIN:				
55 MIN:				
60 MIN:				



Test Run Inspection (Continued)

Vibration Data: In./Sec-Peak	(Readings should be less than .08 In/Sec Peak)		
	Horizontal	VDE	Axial
DE	0.09	0.03	
ODE	0.04	0.02	

Magnetic Center Measurements (Only Applies to Sleeve Bearing Motors)

Magnetic Center line distance from shaft shoulder

Magnetic Center line distance from all the way out mark

Magnetic Center line distance from all the way in mark

Total Motor End Float

Additional photos










Yes, the shaft has been isolated for delivery.

Service Tech name:

Robert Wiley

Service Tech signature:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301