

Job Information

Job #: .137482 Date: June 22, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: CINTAS Motor#:

Name Plate Information

Manufacturer: AO SMITH Enclosure: Open Drop Proof Horsepower/kW: 40

(ODP)

Serial#: Service Factor:

Frame: 365T Rated RPM: 890 Rated Voltage: 230/460

Phase: 3 Rated Amps: 126/64 Cycles: 60

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Worn Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6314

Shaft runout(TIR-Inbound): .0015 Bearing ODE Size: 6212

Retainer condition: Good



Mechanical Inspection (Continued)

Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Slinger If DE undersized, amt.: .097"

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.: .000

Seals ODE condition: Shaft damage: OK Worn

Seals ODE type: Slinger

Bushings/sleeves DE: Ok Seals ODE size:

Bushings/sleeves ODE: Ok Seals ODE (inbound) condition:

> Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 5.9055 Foot flatness: **Pass**

Endbell DE insulated?:

Endbell ODE insulated?:

variation)? Endbell ODE size:

No

Does Air Gap Meet Customer or EASA spec(<10%

4.334

Conclusion

Service Tech name: **BILLY MAYS**

Service Tech signature: