



MILLINGTON, TN

LITTLE ROCK, AR

Job Information

Job #: 134147

Date: January 22,
2018

Priority: —

Authorized OT: No

Authorized by:

Customer Information

Name:

Motor#:

Name Plate Information

Manufacturer:	Enclosure :	Open Drop Proof (ODP)	Horsepower/kW:
Serial#:	Model#:		Service Factor:
Frame:	Rated RPM:		Rated Voltage:
Phase:	Rated Amps:		Cycles:

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: —

Bearings Retainer: Yes

Type of grounding device:

Bearing DE Size: 6309

Shaft runout(TIR-Inbound):

Bearing ODE Size: 6310

Retainer condition: —

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

Mechanical Inspection (Continued)

Seals DE condition : Worn

Brg. Seats DE: Good

Seals DE type: Slinger

If DE undersized, amt.:

Seals DE size:

Brg. Seats ODE: Good

Seals DE (inbound) condition :

If ODE undersized, amt.:

Seals ODE condition : Worn

Shaft damage: OK

Seals ODE type: Slinger

Bushings/sleeves DE: Ok

Seals ODE size:

Bushings/sleeves ODE: Ok

Seals ODE (inbound) condition :

Endbell fits/damage: Good

Foot/Flange condition: Ok

Endbell DE size:

Foot flatness: Pass

Endbell DE insulated?: —

Does Air Gap Meet Customer or EASA spec(<10% variation)?

Endbell ODE size:

Endbell ODE insulated?: —

—

Conclusion

Service Tech name:

Service Tech signature: