

Job Information

Job #: 136534 Date: March 12, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: South treatment plant Motor#:

Name Plate Information

Manufacturer: GE Enclosure: Totally Enclosed Horsepower/kW: 125

Fan Cooled

Serial#: XYS47809A Model#: 5K509SN624 Service Factor: 1.15

Frame: 509LL Rated RPM: 590 Rated Voltage: 480

Phase: 3 Rated Amps: 165 Cycles: 60

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6315

Shaft runout(TIR-Inbound): .001 Bearing ODE Size: 6318

Retainer condition: —



Mechanical Inspection (Continued)

Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Slinger If DE undersized, amt.: .000

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.: .000

Seals ODE condition: Worn Shaft damage: OK

Seals ODE type: Slinger

Bushings/sleeves DE: Ok Seals ODE size:

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 7.481 Foot flatness: Pass

Endbell DE insulated?: No

Endbell ODE size:

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: No Yes

6.301

Conclusion

Service Tech name: BILLY MAYS

Service Tech signature:

BU MAL