

Job Information

Job #: 136785 Date: March 1, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: South treatment plant Motor#:

Name Plate Information

Manufacturer: Limitorque Enclosure: Open Drop Proof Horsepower/kW: 3#

(ODP)

Serial#: 8435 Model#: Service Factor:

Frame: Rated RPM: 1800 Rated Voltage: 480

Phase: 3 Rated Amps: 1.68 Cycles: 60

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6202

Shaft runout(TIR-Inbound): .001 Bearing ODE Size: 6202

Retainer condition: —



Mechanical Inspection (Continued)

Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Slinger If DE undersized, amt.: 00

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.: 00

Seals ODE condition: Shaft damage: Worn OK

Seals ODE type: Slinger

Bushings/sleeves DE: Ok Seals ODE size:

Bushings/sleeves ODE: Ok Seals ODE (inbound) condition:

> Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 1.3786 Foot flatness: **Pass**

Endbell DE insulated?: No

> Does Air Gap Meet Customer or EASA spec(<10% Endbell ODE size: 1.3786

variation)?

Endbell ODE insulated?: No Yes

Conclusion

Service Tech name: Billy Mays

Service Tech signature: