

Job Information

Job #: 137097 Date: April 19, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: XYLEM DEWATERING SOLUTIONS Motor#:

Name Plate Information

Manufacturer: U.S. Enclosure: Weather Protected Horsepower/kW: 125

I (WPI)

Serial#: Service Factor: 1.15

Frame: 445TP Rated RPM: 1190 Rated Voltage: 460

Phase: 3 Rated Amps: 117 Cycles: 60

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 7322

Shaft runout(TIR-Inbound): .002 Bearing ODE Size: 6215

Retainer condition: Good



Mechanical Inspection (Continued)

Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Slinger If DE undersized, amt.: .000

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.: .000

Seals ODE condition: Shaft damage: OK Worn

Seals ODE type: Slinger

Bushings/sleeves DE: Ok Seals ODE size:

Bushings/sleeves ODE: Ok Seals ODE (inbound) condition:

> Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 9.449 Foot flatness: **Pass**

Endbell DE insulated?: No

> Does Air Gap Meet Customer or EASA spec(<10% Endbell ODE size:

variation)? 5.119

Endbell ODE insulated?: No Yes

Conclusion

Service Tech name: Billy mays

Service Tech signature: