

Job Information

Job #: 137406 Date: June 8, 2018

Priority: 1Rush No OT Authorized OT: No Authorized by:

Customer Information

Name: NCI GROUP Motor#:

Name Plate Information

Manufacturer: Allen bradley Enclosure: Open Drop Proof Horsepower/kW: 200

(ODP)

Serial#: B1017688-020002 Model#: Service Factor:

Frame: RI2898z Rated RPM: 1765 Rated Voltage: 460

Phase: 3 Rated Amps: 237 Cycles: 60

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6315

Shaft runout(TIR-Inbound): 001 Bearing ODE Size: 6315

Retainer condition: Good



Mechanical Inspection (Continued)

Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Slinger If DE undersized, amt.: .000

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.: .000

Seals ODE condition: Shaft damage: OK Worn

Seals ODE type: Slinger

Bushings/sleeves DE: Ok Seals ODE size:

Bushings/sleeves ODE: Ok Seals ODE (inbound) condition:

> Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 6.3 Foot flatness: **Pass**

Endbell DE insulated?: No

Endbell ODE insulated?:

variation)? Endbell ODE size: 6.3

Yes

Does Air Gap Meet Customer or EASA spec(<10%

Conclusion

Service Tech name: Billy mays

Service Tech signature:

No