



MILLINGTON, TN

LITTLE ROCK, AR

Job Information

Job #: 137904

Date: August 14, 2018

Priority: —

Authorized OT: No

Authorized by:

Customer Information

Name: KTG

Motor#:

Name Plate Information

Manufacturer: MC

Enclosure : Open Drop Proof (ODP)

Horsepower/kW:

Serial#: 45AUR25250-

Model#:

Service Factor:

Frame:

Rated RPM:

Rated Voltage:

Phase:

Rated Amps:

Cycles:

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good

Bearings Retainer: Yes

Type of grounding device:

Bearing DE Size: 6007

Shaft runout(TIR-Inbound): .001

Bearing ODE Size: 6002

Retainer condition: Good

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

Mechanical Inspection (Continued)

| | | | |
|---------------------------------|-------|--|------|
| Seals DE condition : | None | Brg. Seats DE: | Good |
| Seals DE type: | N/A | If DE undersized, amt.: | .000 |
| Seals DE size: | | Brg. Seats ODE: | Good |
| Seals DE (inbound) condition : | | If ODE undersized, amt.: | .000 |
| Seals ODE condition : | None | Shaft damage: | OK |
| Seals ODE type: | N/A | | |
| Seals ODE size: | | Bushings/sleeves DE: | Ok |
| Seals ODE (inbound) condition : | | Bushings/sleeves ODE: | Ok |
| | | | |
| Endbell fits/damage: | Good | Foot/Flange condition: | Ok |
| Endbell DE size: | 2.436 | Foot flatness: | Pass |
| Endbell DE insulated?: | — | | |
| Endbell ODE size: | 1.260 | Does Air Gap Meet Customer or EASA spec(<10% variation)? | |
| Endbell ODE insulated?: | No | Yes | |

Conclusion

Service Tech name: BILLY MAYS

Service Tech signature:

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254