



MILLINGTON, TN

LITTLE ROCK, AR

Job Information

Job #: 139501

Date: April 8, 2019

Priority: —

Authorized OT: No

Authorized by:

Customer Information

Name: CS3,INC

Motor#:

Name Plate Information

Manufacturer:	BALDOR	Enclosure :	Totally Enclosed Air Over (TEO)	Horsepower/kW:	30
Serial#:	M12H727Y27661	Model#:	1205386822	Service Factor:	1.15
Frame:	324T	Rated RPM:	1775	Rated Voltage:	230/460
Phase:	3	Rated Amps:	96/48	Cycles:	60

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good

Bearings Retainer: Yes

Shaft runout(TIR-Inbound): 00

Bearing DE Size: 6312

Retainer condition: Good

Bearing ODE Size: 6311

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

Mechanical Inspection (Continued)

DE shaft extension :	2.125	Shaft damage:	OK
DE shaft extension keyway:	.5	Shaft Brg. Journal DE:	Good
ODE shaft extension :	N/A	If DE undersized, amt.:	0
ODE shaft extension keyway:	N/A	Shaft damage:	OK
Shaft air Seal DE size:	2.875	Shaft Brg. Journal ODE:	Good
Shaft air Seal ODE size:	2.166	If ODE undersized, amt.:	0
DE Endbell fits/damage:	Good	ODE Endbell fits/damage:	Good
Endbell DE size:	5.119	Endbell ODE size:	4.725
Endbell DE air seal size:	2.9	Endbell ODE air seal size:	2.8
Endbell DE insulated?:	No	Endbell ODE insulated?:	No
Foot flatness:	Pass	Does Air Gap Meet Customer or EASA spec(<10% variation)?	

Conclusion

Yes

Machine
work
needed: NONE REQ'D

Service BILLY MAYS

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254