



MILLINGTON, TN

LITTLE ROCK, AR

Job Information

Job #: 140021

Date: June 24, 2019

Priority: —

Authorized OT: No

Authorized by:

Customer Information

Name: HSLR

Motor#:

Name Plate Information

Manufacturer: Enclosure : Open Drop Proof (ODP) Horsepower/kW:

Serial#: Model#: Service Factor:

Frame: Rated RPM: Rated Voltage:

Phase: Rated Amps: Cycles:

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Worn

Bearings Retainer: Yes

Shaft runout(TIR-Inbound):

Bearing DE Size: 6316

Retainer condition: Good

Bearing ODE Size: 6314

WEST TENNESSEE

7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS

6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

Mechanical Inspection (Continued)

DE shaft extension :	2.881	Shaft damage:	Salvageable
DE shaft extension keyway:	.760	Shaft Brg. Journal DE:	Undersized
ODE shaft extension :	2.570	If DE undersized, amt.:	-.0004
ODE shaft extension keyway:	N/A	Shaft damage:	OK
Shaft air Seal DE size:	3.151 / 3.609	Shaft Brg. Journal ODE:	Good
Shaft air Seal ODE size:	2.754 / 3.215	If ODE undersized, amt.:	.000
DE Endbell fits/damage:	Good	ODE Endbell fits/damage:	Good
Endbell DE size:	6.693	Endbell ODE size:	5.9055
Endbell DE air seal size:		Endbell ODE air seal size:	
Endbell DE insulated?:	No	Endbell ODE insulated?:	No
Foot flatness:	Pass	Does Air Gap Meet Customer or EASA spec(<10% variation)?	

Conclusion

Yes

Machine
work
needed: DE brg journal is .0004 undersize

Service Billy Mays

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254