



MILLINGTON, TN

LITTLE ROCK, AR

Job Information

Job #: 140146

Date: July 11, 2019

Priority: —

Authorized OT: No

Authorized by:

Customer Information

Name: HSLR

Motor#:

Name Plate Information

Manufacturer: U.S.MOTOR

Enclosure : Open Drop Proof (ODP)

Horsepower/kW:

Serial#:

Model#:

Service Factor:

Frame:

Rated RPM:

Rated Voltage:

Phase:

Rated Amps:

Cycles:

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good

Bearings Retainer: Yes

Shaft runout(TIR-Inbound): .0005

Bearing DE Size: FAG7220

Retainer condition: Good

Bearing ODE Size: SKF6211

WEST TENNESSEE

7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS

6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

Mechanical Inspection (Continued)

DE shaft extension :	2.374	Shaft damage:	OK
DE shaft extension keyway:	.375	Shaft Brg. Journal DE:	Good
ODE shaft extension :	2.376 HUB ID	If DE undersized, amt.:	.0000
ODE shaft extension keyway:	.375 HUB KEY	Shaft damage:	OK
Shaft air Seal DE size:	N/A	Shaft Brg. Journal ODE:	Good
Shaft air Seal ODE size:	2.163	If ODE undersized, amt.:	.0000
DE Endbell fits/damage:	Good	ODE Endbell fits/damage:	Good
Endbell DE size:	7.087	Endbell ODE size:	3.9376
Endbell DE air seal size:	///////	Endbell ODE air seal size:	////////
Endbell DE insulated?:	No	Endbell ODE insulated?:	No
Foot flatness:	Pass	Does Air Gap Meet Customer or EASA spec(<10% variation)?	

Conclusion

Yes

Machine
work
needed: CUT BEARINGS
ALL FITS CHECK GOOD
NO MACHINE WORK REQUIRED

Service BILLY MAYS

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254