



MILLINGTON, TN

LITTLE ROCK, AR

Job Information

Job #: 140148

Date: July 12, 2019

Priority: —

Authorized OT: No

Authorized by:

Customer Information

Name: HSLR

Motor#:

Name Plate Information

Manufacturer:	Enclosure :	Open Drop Proof (ODP)	Horsepower/kW:
Serial#:	Model#:		Service Factor:
Frame:	Rated RPM:		Rated Voltage:
Phase:	Rated Amps:		Cycles:

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition:	Good	Bearings Retainer:	Yes
Shaft runout(TIR-Inbound):	.0005	Bearing DE Size:	6316
Retainer condition:	Good	Bearing ODE Size:	6316

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

Mechanical Inspection (Continued)

DE shaft extension :	2.874	Shaft damage:	OK
DE shaft extension keyway:	..750	Shaft Brg. Journal DE:	Good
ODE shaft extension :	N/a	If DE undersized, amt.:	.000
ODE shaft extension keyway:	N/a	Shaft damage:	OK
Shaft air Seal DE size:	3.591	Shaft Brg. Journal ODE:	Good
Shaft air Seal ODE size:	3.591	If ODE undersized, amt.:	.000
DE Endbell fits/damage:	Good	ODE Endbell fits/damage:	Good
Endbell DE size:	6.6935	Endbell ODE size:	6.695
Endbell DE air seal size:	3.170	Endbell ODE air seal size:	3.170
Endbell DE insulated?:	No	Endbell ODE insulated?:	No
Foot flatness:	Pass	Does Air Gap Meet Customer or EASA spec(<10% variation)?	

Conclusion

Yes

Machine work needed: BORE AND SLEEVE O.D.E. ENDBELL .
CUT BEARINGS

Service BILLY MAYS

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254