



MILLINGTON, TN

LITTLE ROCK, AR

## Job Information

Job #: 141814

Date:

Priority: —

Authorized OT: No

Authorized by:

## Customer Information

Name: Hershey

Motor#:

## Name Plate Information

Manufacturer:	SEW Eurodrive	Enclosure :	Open Drop Proof (ODP)	Horsepower/kW:	9.2
Serial#:	KAF127R87	Model#:		Service Factor:	
Frame:		Rated RPM:	1775	Rated Voltage:	380/420
Phase:	3	Rated Amps:	18/70	Cycles:	50/60

Special design: No

## Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition:	Other	Bearings Retainer:	Yes
Type of grounding device:	None	Bearing DE Size:	6309
Shaft runout(TIR-Inbound):	.0001	Bearing ODE Size:	6209
Retainer condition:	—		

**WEST TENNESSEE**  
7030 Ryburn Drive  
Millington, TN 38053  
Phone 901-873-5300  
Fax 901-873-5301

**CENTRAL ARKANSAS**  
6812 Lindsey Rd.  
Little Rock, AR 72206  
Phone 501-375-9178  
Fax 501-375-4254

## Mechanical Inspection (Continued)

Seals DE condition :	Worn	Brg. Seats DE:	Undersized
Seals DE type:	Other	If DE undersized, amt.:	.001
Seals DE size:	40 62 7	Brg. Seats ODE:	Undersized
Seals DE (inbound) condition :	Damaged	If ODE undersized, amt.:	001
Seals ODE condition :	Worn	Shaft damage:	OK
Seals ODE type:	Slinger		
Seals ODE size:	1374 3198	Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :	Damaged	Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	3.9374	Foot flatness:	Pass
Endbell DE insulated?:	No	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
Endbell ODE size:	3.3468		
Endbell ODE insulated?:	No	Yes	

## Conclusion

Service Tech name: Jeremy Yarbrough

Service Tech signature:

