

Job Information

Job #:	94194				Date:	April 21, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Arkansas industrial machine	Motor#:

Name Plate Information

Manufacturer:	Siemens	Enclosure :	Totally Enclosed Fan Cooled	Horsepower/kW:	224
Serial#:		Model#:	1LA8 315-4AB91-2315	Service Factor:	1.0
Frame:	315	Rated RPM:	1785/1787	Rated Voltage:	440/460
Phase:	3	Rated Amps:	350/335	Cycles:	60

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition:	Good	Bearings Retainer:	Yes
Type of grounding device:		Bearing DE Size:	Nu218E
Shaft runout(TIR-Inbound):		Bearing ODE Size:	Nu218e

Retainer condition: Good

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Mechanical Inspection (Continued)

Seals DE condition :	Brittle	Brg. Seats DE:	Good
Seals DE type:	Slinger	If DE undersized, amt.:	
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	
Seals ODE condition :	Brittle	Shaft damage:	ОК
Seals ODE type:	Slinger		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Bad	Foot/Flange condition:	Ok
Endbell DE size:	6.3004	Foot flatness:	Pass
Endbell DE insulated?:	No	Doos Air Gon Most Cu	$t_{\rm const}$ or EASA approx($<10\%$
Endbell ODE size:	6.3001	variation)?	stomer or EASA spec(<10%
Endbell ODE insulated?:	No	_	

Conclusion

Service Tech name:

Terrence Holland

Service Tech signature:

Penere foll of

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254