

Job Information

Job #: 94229 Date: May 16, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Entergy whitebluff Motor#:

Name Plate Information

Manufacturer: Limit torque Enclosure: Open Drop Proof Horsepower/kW: .7

(ODP)

Serial#: 713107-SA Model#: Service Factor:

Frame: L56 Rated RPM: 1700 Rated Voltage: 230/460

Phase: 3 Rated Amps: 4.6/2.3 Cycles: 60

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: No

Type of grounding device: Bearing DE Size: Koyo 6203/2Z

Shaft runout(TIR-Inbound): Bearing ODE Size: Koyo 6203/2Z

Retainer condition: —



Mechanical Inspection (Continued)

Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: N/A If DE undersized, amt.:

Seals DE size: 1-JC-112-162-8-68 Brg. Seats ODE: Good

Seals DE (inbound) condition: Worn If ODE undersized, amt.:

Seals ODE condition: None Shaft damage: OK

Seals ODE type: N/A

Bushings/sleeves DE: Ok Seals ODE size:

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: Foot flatness: Pass

Endbell DE insulated?: —

Endbell ODE size:

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: - -

Conclusion

Service Tech name: Terrence Holland

Service Tech signature:

Lever Collect