



MILLINGTON, TN

LITTLE ROCK, AR

Job Information

Job #: 94232

Date: May 16, 2018

Priority: —

Authorized OT: No

Authorized by:

Customer Information

Name: Entergy White Bluff

Motor#:

Name Plate Information

Manufacturer:	Limitorque	Enclosure :	Totally Enclosed Non-Ventilated	Horsepower/kW:	.7
Serial#:		Model#:	371Q2170M-SF	Service Factor:	1.0
Frame:	L56	Rated RPM:	1700	Rated Voltage:	460
Phase:	3	Rated Amps:	2.3	Cycles:	60

Special design: Yes

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good

Bearings Retainer: No

Type of grounding device:

Bearing DE Size: 6203ZZ

Shaft runout(TIR-Inbound):

Bearing ODE Size: 6203ZZ

Retainer condition: —

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

Mechanical Inspection (Continued)

Seals DE condition :	None	Brg. Seats DE:	Undersized
Seals DE type:	N/A	If DE undersized, amt.:	.6691
Seals DE size:		Brg. Seats ODE:	Undersized
Seals DE (inbound) condition :		If ODE undersized, amt.:	.6690
Seals ODE condition :	None	Shaft damage:	OK
Seals ODE type:	N/A	Bushings/sleeves DE:	Ok
Seals ODE size:		Bushings/sleeves ODE:	Ok
Seals ODE (inbound) condition :			
Endbell fits/damage:	Bad	Foot/Flange condition:	Ok
Endbell DE size:	1.5764	Foot flatness:	Pass
Endbell DE insulated?:	No	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
Endbell ODE size:	1.5761		
Endbell ODE insulated?:	No		

Conclusion

Service Tech name: RHR

Service Tech signature:

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254