

Job Information

Job #: 94261 Date: May 1, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: L'Oréal Motor#:

Name Plate Information

Manufacturer: CEMP Enclosure: Open Drop Proof Horsepower/kW: 22KW

(ODP)

Serial#: Service Factor:

Frame: Rated RPM: 3528 Rated Voltage: 230/460

Phase: 3 Rated Amps: 69.6/36.3 Cycles: 60

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Aegis Ring Bearing DE Size: 6310ZZ C3

Shaft runout(TIR-Inbound): Bearing ODE Size: 6310ZZ C3

Retainer condition: Good



Mechanical Inspection (Continued)

Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Slinger If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: OK Worn Shaft damage:

Seals ODE type: Slinger

Bushings/sleeves DE: Ok Seals ODE size:

Bushings/sleeves ODE: Ok Seals ODE (inbound) condition:

> Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 4.3313 Foot flatness: **Pass**

Endbell DE insulated?:

Endbell ODE insulated?:

Does Air Gap Meet Customer or EASA spec(<10% variation)? Endbell ODE size: 4.3311

Conclusion

Service Tech name: **Robert Wiley**

Service Tech signature:

WEST TENNESSEE