



MILLINGTON, TN

LITTLE ROCK, AR

Job Information

Job #: 94278

Date: May 7, 2018

Priority: 1A Rush/OT

Authorized OT: No

Authorized by:

Customer Information

Name: Lexicon

Motor#:

Name Plate Information

Manufacturer: Reuland

Enclosure : Open Drop Proof (ODP)

Horsepower/kW: 4

Serial#: 823471R-1

Model#: 13273

Service Factor:

Frame: WEO-215/H4

Rated RPM: 1800/53

Rated Voltage: 230/460

Phase: 3

Rated Amps: 10.6/5.3

Cycles: 60

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good

Bearings Retainer: No

Type of grounding device:

Bearing DE Size: 6306/2Z

Shaft runout(TIR-Inbound):

Bearing ODE Size: 6306/2Z

Retainer condition: —

WEST TENNESSEE

7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS

6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254

Mechanical Inspection (Continued)

Seals DE condition :	None	Brg. Seats DE:	Good
Seals DE type:	N/A	If DE undersized, amt.:	
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	
Seals ODE condition :	None	Shaft damage:	OK
Seals ODE type:	N/A	Bushings/sleeves DE:	Ok
Seals ODE size:		Bushings/sleeves ODE:	Ok
Seals ODE (inbound) condition :			
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	2.8353	Foot flatness:	N/A
Endbell DE insulated?:	No	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
Endbell ODE size:	2.8348		
Endbell ODE insulated?:	No		

Conclusion

Service Tech name: Terrence Holland

Service Tech signature:

