

Job Information

Job #: 94332 Date: May 21, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Aft Motor#:

Name Plate Information

Manufacturer: BARTEC VARNOST Enclosure: Totally Enclosed Horsepower/kW:

Fan Cooled

Serial#: Model#: Service Factor:

Frame: Rated RPM: Rated Voltage:

Phase: Rated Amps: Cycles:

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Aegis Bearing DE Size: 6310ZZC3

Shaft runout(TIR-Inbound): Bearing ODE Size: 6310ZZC3

Retainer condition: —



Mechanical Inspection (Continued)

Seals DE condition: None Brg. Seats DE: Good

Seals DE type: Other If DE undersized, amt.:

Seals DE size: 50 72 8 Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.: Good

Seals ODE condition: OK None Shaft damage:

Seals ODE type: Other

Bushings/sleeves DE: Ok Seals ODE size: 50 72 8

Bushings/sleeves ODE: Ok Seals ODE (inbound) condition: Good

> Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 4.3317 Foot flatness: **Pass**

Endbell DE insulated?: No

> Does Air Gap Meet Customer or EASA spec(<10% Endbell ODE size: 4.3311

variation)?

Endbell ODE insulated?: No

Conclusion

Service Tech name: **Robert Wiley**

Service Tech signature: