

Job Information

Job #: 94344 Date: May 25, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: SYNOVOS-L"OREAL Motor#:

Name Plate Information

Manufacturer: VELOCITA Enclosure: Totally Enclosed Horsepower/kW: 27KW

Fan Cooled

Serial#: Service Factor:

Frame: Rated RPM: Rated Voltage:

Phase: Rated Amps: Cycles:

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6312ZZC3

Shaft runout(TIR-Inbound): Bearing ODE Size: 6312ZZC3

Retainer condition: —



Mechanical Inspection (Continued)

Seals DE condition: None Brg. Seats DE: Good

Seals DE type: Other If DE undersized, amt.:

Seals DE size: 60 80 8 Brg. Seats ODE: Good

Seals DE (inbound) condition: Good If ODE undersized, amt.:

Seals ODE condition: None Shaft damage: OK

Seals ODE type: Other

Seals ODE size: 60 80 8

Seals ODE (inbound) condition: Good Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 5.1190 Foot flatness: Pass

Endbell DE insulated?: —

Endbell ODE insulated?:

Does Air Gap Meet Customer or EASA spec(<10% variation)?

Lilubeli ODL 3ize. 3.1100

Conclusion

Service Tech name: Robert Wiley

Service Tech signature:

hoser When