

Job Information

Job #: 94473 Date: July 3, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: AFT Motor#:

Name Plate Information

Manufacturer: Grundfos Enclosure: Totally Enclosed Horsepower/kW: 5

Fan Cooled

Serial#: 85902264 Model#: Service Factor:

Frame: Rated RPM: 2910-2930 Rated Voltage: 380/415

Phase: 3 Rated Amps: Cycles:

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: No

Type of grounding device: Bearing DE Size: 6306ZZ C4

Shaft runout(TIR-Inbound): Bearing ODE Size: 7306 BF

Retainer condition: —



Mechanical Inspection (Continued)

Seals DE condition: None Brg. Seats DE: Good

Seals DE type: N/A If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: None Shaft damage: OK

Seals ODE type: N/A

Bushings/sleeves DE: Ok Seals ODE size:

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 2.8356 Foot flatness: Pass

Endbell DE insulated?: No

Endbell ODE size:

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: No –

2.8355

Conclusion

Service Tech name: Lynn McDonald

Service Tech signature:

Jyn MD nald